


DIGIROCK-RBOV

DIGITAL ROCKWELL, BRINELL & VICKERS
HARDNESS TESTER



OPERATIONAL MANUAL

CE

BMS Bulut Makina Sanayi Ve Ticaret Ltd. Şti.


İkitelli Organize Sanayi Bölgesi Dolapdere Sanayi Sitesi

Ada 4 No : 7-9 Başakşehir / İSTANBUL-TURKEY

Phone : +90 212 671 02 24 / 671 02 25 Fax : +90 212 671 02 26

web : www.bulutmak.com e-mail : bms@bulutmak.com

1. Technical Features	4
2. Standart Accessories	4
2.1 Optional Accessories.....	4
3. Unpacking Of Equipment	4
4. Setting Into Operation For Rockwell Hardness Testing	4
5. Testing	5
6. Adjusting Loading Speed	5
7. Rockwell Hardness Testing (EN 6508-1,ASTM E18).....	5
8. Brinell Hardness Testing (EN 6506-1,ASTM E10)	6
9. Setting Into Operation For Brinell Hardness Testing.....	7
10. Sample of Reading Indentation.....	7
11. Vickers Hardness Testing (EN-6507-1,ASTM E-92)	7
12. Setting Into Operation For Vickers Hardness Testing	7
13. Sample Of Reading Indentation	7
14. Part List.....	9
15. SLIDING TABLE OP : 200	10
16. Test Method	11
17. Prior To Test	12
18. Choosing The Test Load.....	12
18.1 Main Screen	12
19. Testing	12
19.1 Brinell Test	13
19.2 Vickers Test.....	14
20. Test Method	14
21. Records.....	15
22. Settings	15
23. Calibration.....	17
24. Important Notice.....	17
25. Directions	18
25.1 ADDRESS	22
25.2 CUSTOMER.....	23
25.3 HARDNESS TEST	24
25.4 REPORTS	31



1. Technical Features

Pre-load(kgf)	10
Loads (kgf)	60,100,150 kgf Rockwell 62.5 ,187.5 kgf Brinell 30 kgf Vickers
Load selection	By load selector disc
Test methods	Rockwell, Brinell & Vickers
Load application	Hydraulic
Max. testing height	With sliding table 140 mm , without sliding table 240 mm
Throat	145 mm
Machine dimensions	780X550X360 mm
Case dimensions	950x700x350 mm
Weight (net/gross)	95 / 125 kg
Optical System	75X magnification for Brinell 150X magnification for Vickers
Power	220 V, 50Hz

2. Standart Accessories

Rockwell Diamond cone indenter
Vickers Diamond pyramide indenter
1/16" ball indenter
2.5mm ball indenter
HRC test block
HRB test block
HB 2.5 / 187.5 Brinell test block
Flat testing table
V anvil for round parts
Hardness Conversion Table
Wooden case for accessories
Cover
Allen spanners
Operational Manual
Calibration Certificate
Digital Camera

2.1 Optional Accessories

1/8" , 1/4" , 1/2" ball indenters
250,200,130,100 mm test tables
Spot testing anvil
Spring loaded clamping device

3. Unpacking Of Equipment

Unscrew fixing steel sheet plates of upper side to wooden base of case and hold up upper side of wooden case by means of carrying handles. Take out two M8 bolts fastening equipment to lower wooden case. Locate equipment on a special table (see drawing of table enclosed) and fasten two M8 bolts by means of eye bull putting on flat testing table. Open left cover. Take out wooden safety parts. Take out also 3 off M6 bolts of top cover by means of 5 mm special alyen key which is in accessory box. Hold top cover up with care. Pay attention not to touch Rockwell Dial gauge. Take out plastic safety parts. Equipment is now ready for testing.

4. Setting Into Operation For Rockwell Hardness Testing

Before starting to test, load application lever (KL2) (8) has to be in starting position (see drawing and picture). Locate part to be tested on testing table, insert indenter to holder (ML3) (5) and choose load by means of load selector disc (VL1) (14) (according to testing method in attached table)

5. Testing

As soon as indenter touches on part, actuating main spindle (ML1) (12) by means of arms (SM1) (13) , bar graph starts to increase.

When %100 position achieved, APP.TOTAL LOAD message shown. Then apply total load application lever (KL2) to forward (see drawing) and follow the message on display .You will see DWELLING TIME when total load fully obtained. Wait until RELEASE THE LOAD message shown and then take back lever (KL2) to starting position. And read TEST RESULT on display.

6. Adjusting Loading Speed


Load application is adjusted by hydraulic system. Hydraulic oil is filled at our works and hydraulic application speed is adjusted at our works. (But, working at extremely high temperatures or during transportation due to wrong handling if oil is reduced you may add some oil again. To do this, open left cover. There are two bolts on hydraulic piston (PS1) Take out bolt on the left. **(A1)** Add some oil (Tellus 37 or similiar) While adding oil, you can use load application lever (KL2) (8) forward and backward. This helps oil to settle down easily. You can adjust hydroulic speed, by allen bolt on the right. **(B1)** If you turn this bolt clockwise laod application speed is decreased, If you turn anti clockwise it is increased.



7. Rockwell Hardness Testing (EN 6508-1, ASTM E18)


Rockwell Hardness testing method is evaluated from penetration depth of 120° diamond cone or ball indenter with different dias (please refer to table enclosed).

Below application shows working procedures using Rockwell diamond cone (HRC-HRA etc)



Nr	Symbol	Description
1	0	120 ° Diamond cone
2	0	Radius of diamond tip= 0,2 mm
3	F ₀	Pre-Load
4	F ₁	Additional Load
5	F	Total load F ₀ + F ₁
6	t ₀	Depth of penetration under pre-load, mm
7	t ₁	Depth of penetration under additional load, mm
8	t _b	Increase in depth of penetration from F ₁ to F ₀ , mm
9	e	Equality as of 0,002 mm increase of depth of penetration e= t _b / 0,002
10	0	Rockwell hardness = 100-e

Below application shows working procedures using 1/16" ball indenter (HRB etc)



Nr	Symbol	Description
1	D	Ball dia=1/16 " =1,5875 mm
3	F ₀	Pre-load
4	F ₁	Additional load
5	F	Total load =F ₀ +F ₁
6	t ₀	Depth of penetration under pre-load, mm
7	t ₁	Depth of penetration under additional load, mm
8	t _b	Increase in depth of penetration from F ₁ to F ₀ , mm
9	e	Equality as of 0,002 mm increase of depth of penetration e= t _b / 0,002
10	HRB/HRF	Rockwell hardness= 130-e

8.Brinell Hardness Testing (EN 6506-1,ASTM E10)

Brinell Hardness testing method is made by different balls depending (for DIGIROCK-RBOV only 2,5 mm ball) on material type, thickness and loads applied. Diameters of ball indentations can be evaluated by optical system built-in hardness tester.

Relations with thickness of specimen,ball dia and material shown in related the table

Thickness of material (mm)	Ball dia(mm)	P=30D2 Steel,iron, cast iron	P=10D2 Brass, Bronze, Copper, Aluminium	P=D2 Soft copper	P=5D2 Lead
6 mm and up	10	3.000 kgf	1.000 kgf	500 kgf	250 kgf
3 mm and up	5	750 kgf	250 kgf	125 kgf	62,5 kgf
1,2 mm and up	2,5	187,5 kgf	62,5 kgf	31,25 kgf	15,625 kgf
0,5 mm and up	1	30 kgf	10 kgf	5 kgf	-

9. Setting Into Operation For Brinell Hardness Testing

Locate 5X objective (16) on optical system.

Before starting to test, load application lever (KL2) (8) has to be in starting position (see drawing and picture) Locate part to be tested on testing table (10), **Moving lever of sliding table (11) to the left, assure testing table (10) to touch stoping bolt.**

Insert 2,5 mm ball indenter to holder (ML3) (5) and choose load by means of load selector disc (VL1) (14) (according to table shown above)

IMPORTANT: For Brinell and Vickers tests quick lift lever (7) always must be in forward position touching the stop pin.

Apply pre-load and total load as described in Rockwell testing.

Follow movement of big pointer until it stops. Wait 3-5 sec. more. Then take back lever (KL2) (8) to starting position. Move quick lift lever (7) from right to left until it touches stop pin.

Move quick lift lever (7) from right to left until it touches stoping pin. (in this case indenter to be separated from the surface of the part to be tested)

In this case, move the lever of sliding table to the right carefully (11) until testing table touches micrometer.

10. Sample of Reading Indentation

Drawing : OP-2

Adjust, measuring moving line by means of micrometer of digital camera (2) until it touches leftest side of indentation. Then, move, measuring line from left to right until it touches rightest side of indentation. Than calculate value.

11. Vickers Hardness Testing (EN-6507-1, ASTM E-92)

Vickers Hardness testing method is made by 136° Vickers pyramid indenter. Vickers indentation can be evaluated by optical system built-in hardness tester.

12. Setting Into Operation For Vickers Hardness Testing

Locate 10X objective (16) on optical system

Assure all points same as Brinell test before start to operation.

Insert Vickers diamond indenter to holder (ML3) (5) and choose 30 kgf load by means of load selector disc (VL1) (14)




Actuate Vickers test using same steps as per mentioned for Brinell test.

13. Sample Of Reading Indentation

Drawing : OP-3

Adjust, measuring moving line by means of micrometer of digital camera (2) until it touches leftest side of indentation. Then, move, measuring line from left to right until it touches rightest side of indentation. Than calculate value.

DIGIROCK-RBOV




14.Part List

DIGIROCK-RBOV	
2	
ML3	Indenter holder
LR1	Linear bearing
KV2	Bush for linear bearing
UC1	Indentor
TP1	Clamping cap
3	
MV1	Lever
MV2	Pre-load lever
ML3	Side bushings
AS1	Hook
4	
KF1	Cage
KP1	Right cover
KP3	Left cover
VL1	Load selector disc
AG1	30 kg. Weight
AG2	60 kg. :Weight
AG3	62,5 kg. Weight
AG4	100 kg. Weight
AG5	150 kg. Weight
AG6	87,5 kg. Weight
5	
EK1	Load application system
PS1	Hydraulic damper piston
HD1	Hydraulic oil
KV3	Damper pot
KL2	Load application lever
6	
KP2	Top cover
SP1	Rockwell dial gauge
OP-200 and 300	
OP-201	Fixing bushing for optical system
OP-209	Lever of sliding table
OP-301	Elevating screw
OP-302	Nut
OP-304	Quick lift lever

15.SLIDING TABLE OP : 200

SLIDING TABLE OP : 200



16. Test Method

Test Method	Indentor	Pre-load (kgf)	Total load (kgf)	Field of application
HRA	Diamond cone	10	60	Surface hardened parts with thin cases ($\geq 0,4$ mm)
HRB	1/16" ball	10	100	Non ferrous metals, unhardened steels
HRC	Diamond cone	10	150	Hardened steels
HRD	Diamond cone	10	100	Surface hardened parts with medium cases
HRE	1/8" ball	10	100	Aluminium and magnesium alloys, antifriction metals, synthetic metals
HRF	1/16" ball	10	60	Annealed copper alloys, thin sheet metals ($\geq 0,6$ mm)
HRG	1/16" ball	10	150	Phosphor-bronze, malleable iron of medium hardness
HRH	1/8" ball	10	60	Aluminium, zinc, lead, grinding stones
HRK	1/8" ball	10	150	Antifriction and other metals of very low hardness
HRL	1/4" ball	10	60	As HRK and hard rubber
HRM	1/4" ball	10	100	As HRK and HRL, laminated wood
HRP	1/4" ball	10	150	HRK, HRL or HRM and synthetic materials
HRR	1/2" ball	10	60	
HRS	1/2" ball	10	100	
HRV	1/2" ball	10	150	As HRK, HRL, HRM, HRP, HRR or HRS
HR 15 N HR 30 N HR 45 N	Diamond cone	3	15 30 45	As HRA, HRC or HRD, but especially thin case depth ($\geq 0,18$ mm)
HR15T HR30T HR45T	1/16" ball	3	15 30 45	As HRB, HRF or HRG but especially for thin sheet metals ($\geq 0,25$ mm)
HR15W HR30W HR45W	1/8" ball	3	15 30 45	For metals with very low hardness and for very thin cases, for example thin linings of antifriction metals, HRX and HRY especially for sintered metals
HR15X HR30X HR45X	1/4" ball	3	15 30 45	
HR15Y HR30Y HR45Y	1/2" ball	3	15 30 45	


17. Prior To Test

Pay attention load application lever (KL2) is in starting position. Using table, choose suitable indenter according to test method to be applied. Locate indenter on holder (ML3) carefully and gently tighten allen screw using allen key.

18. Choosing The Test Load

Choose suitable Rockwell test load according to table 2 using load selector disc (VL1) **(In this position, load application lever (KL2) must be in starting position)**. Locate part to be tested on testing anvil. (TA1)

18.1 Main Screen







19. Testing



Switch on equipment by ON/ OFF button. To raise main spindle (ML1) by means of arms (SM1), as soon as indenter touches on part to be tested, bar graph starts to increase.





When %100 position achieved, APP. TOTAL LOAD message shown. Then apply total load application lever (KL2) to forward (see drawing) and follow the message on display. You will see DWELLING TIME when total load fully obtained. Wait until RELEASE THE LOAD message shown and then take back lever (KL2) to starting position. And read TEST RESULT on display.



When TESTING message with DWELLING TIME is over, RELEASE THE LOAD message shown. When you take back lever (KL2) to start position, TEST RESULT shown on display, When required, by pushing  button, conversion of existing test method is indicated as shown. Using  or  buttons others converted test methods can be reached. If  button pressed, only existing test method shown.

19.1 Brinell Test



For optical reading, press button  and write value shown on eyepiece. Press button . Then, press button  again and write value shown on eyepiece once more. Then press  button. HB Brinell value will be shown.

For Brinell tests 5X magn. objective to be used.

19.2 Vickers Test




For optical reading, press button 5 and write value shown on eyepiece.

Press buton. Then, press button 5 again and write value shown on eyepiece once more. Then press button

Vickers value will be shown

For Vickers tests 10X magn. objective to be used.









20. Test Method






Using buttons, TEST METHOD menu obtained. And pressing 6 or 1 buttons required test method can be reached.




21.Records

Using   buttons RECORDS menu reached. Using  or  Buttons, **NO, NAME, REC NO, DELETE** and **INSP** positions obtained. For example to change RECORD NO,  button pressed, using  or  buttons, RECORD NO changed. Pushing  button, it is recorded. Recording for **NAME, REC NO, DELETE** and **INSP** can be actuated by similiar procedures.



When required, pressing  or  buttons, INS position obtained. Pushing  button, all records reached. At the same time Min, Max. And Avg values can be seen according to average value.

When you push , you can print all data in the memory, page by page.

NOTICE: Memory capacity 2500 datas in 50 blocks.

22.Settings












By pressing,   buttons **SETTINGS** menu reached. Using  or  buttons, settings for **printer, date/time, average qty, dwelling, factory settings, lower test limit, upper test limit, language** can be made as shown in related pictures

23. Calibration



Using   buttons, **CALIBRATION** reached. If you push  button, ENTER PASSWORD message shown. If you enter correct password, using   buttons, method for calibration chosen. Pushing  button, upper block value chosen and pushing  button, block value entered.

4 tests made on test block, if values suitable, accepted.

As of next step, in same test method, lowest test block chosen and block value entered. Now calibration finished.

24. Important Notice

During calibration, 2 point calibration system used. Therefore, for each calibration, upper and lowest test blocks must be chosen according to test methods. For example, for HRC method, upper block value 62-65 HRC, lowest block value 22-25 HRC can be chosen.

Your equipment is calibrated under related EN norms. You do not need to calibrate the equipment again. But, if required, calibration can be made using EN norms by expert persons under suitable conditions. In case of making mistakes during calibration, we recommend to go SETTINGS menu and use FACTORY SETTINGS function. Then, you can return original calibrated values.

25.Directions

Hardness Tester software OPTOBUL3

Once installed, the program is first opened Activation Code input window appears.

Product ID
31502175-EGGC-4662-1189

Activation Code


Last 89 days to get activation code !
Please get activation code.

Tel: +90 505 422 18 48

To Purchase software please contact with
the following email address;
bms@bulutmak.com

Bulut Makina - ISTANBUL/TURKEY
Tel : +90 212 671 02 24

Selected Language
English



"	1	2	3	4	5	6	7	8	9	0	*	.	Backspace
Tab	Q	W	E	R	T	Y	U	I	O	P	Ğ	Ü	Enter
Caps	•	A	S	D	F	G	H	J	K	L	Ş	İ	
Shift	Ctrl	Z	X	C	V	B	N	M	Ö	Ç	.	Shift	.

After entering this code "Continue" button.

Login window, the first user to setup the following window: BMS, Password: Enter BMS. (In later entries, pre-defined user name and password to enter).

Year: 2010

Login: bms

Password: xxxx

Selected Language: English


UK Flag


Login Cancel

Virtual Keyboard: S (highlighted)


Main Window the following menu headings Optobul3 are common;


- 1-Address information
- 2-Customer Information
- 3-Hardness Test procedures,
- 4-Logged; program user,
- 5-User management,
- 6-Database Backup and Restore
- 7-Language Selection,
- 8-Program update,
- 9-Program exit





The first step, go to Main Window from the user and the program will use the item of the menu descriptions of people do. Name and Surname details will be written here, test reports "test," information will be used as.

To define a new user, press  New button once, then Login, Password, Name and Last Name boxes to fill. User rights determine and record button.

To change a user's information registered in the list below select the name you want and make changes and  save them press.

25.1 ADDRESS

From the main menu by pressing the Address button, enter your company address information. First, press the New button, fill in the blank field and press the Save button.



Address Info

New Save Delete Language Close

Please press new button to create New Adres Details

Customer bulut

Address 1 İstanbul

Address 2

Contact

Email

Town

City

Country

Tel

Fax

LOGO

Logo seç

Logo sil

Yaklaşık ölçüler
9,16 x 7,29 cm

" 1 2 3 4 5 6 7 8 9 0 * - Backspace

Tab Q W E R T Y U I O P Ğ Ü @

Caps A S D F G H J K L Ş İ

Shift Ctrl Z X C V B N M Ö Ç . Shift ,

Space

25.2 CUSTOMER

From the main menu by pressing customer, enter the customer address information. First, press the New button, Fill in the blank field and press the Save button.



Customer Info [X]

New Save Delete Refresh Language [v] Close

Please press new button to create New Customer

Customer [Please press new button to create New Customer]

Address 1 []

Address 2 []

Contact Person []

Email []

Country []

City []

Town []

Tel []

Fax []

Customer	Address 1	Address 2	Contact Person
bms	ist		
test			


"	1	2	3	4	5	6	7	8	9	0	*	.	Backspace
Tab	Q	W	E	R	T	Y	U	I	O	P	Ğ	Ü	Enter
Caps	●	A	S	D	F	G	H	J	K	L	Ş	İ	Enter
Shift	Ctrl	Z	X	C	V	B	N	M	Ö	Ç	.	Shift	.
Space													

25.3 HARDNESS TEST

From the main menu, press the test and measurement from the screen you make the transition to the screen the following window fill in the fields and "forward" button.

System, load calibration and calibration as will be made with the display settings. Do not need them to do initial setup.

Selected

English 

Brinell Hardness Tester

Please select what you want

- Load Calibration
- Calibration and Video Adjustment
- Measure

The Company name for Test
test

The Material for Test
u

Number of Test: 1 Waiting time for Loading: 8


Objective: 14

Brinell

Virtual Keyboard:

"	1	2	3	4	5	6	7	8	9	0	*	.	Backspace
Tab	Q	W	E	R	T	Y	U	I	O	P	Ğ	Ü	Enter
Caps	A	S	D	F	G	H	J	K	L	Ş	İ	Enter	
Shift	Ctrl	Z	X	C	V	B	N	M	Ö	Ç	.	Shift	.
Space													

Test Method section ball-diameter, Load, objective, lower limit and upper limit, check their values.



Measurement and Test tab, you can make measurement by pressing Test button. After pressing Test button please wait until the machine completes its process and shows you the figure below.

test, Part : u

Settings **Measurement**

Brinell 10 / 3000

D1 μm - D2 μm

Lower Limit Upper Limit
200,00 450,00

Test Data Manual Indenter Movement **Test** Sensitive Tes

GENERAL LOAD/CELL UPPER SENSOR LOWER SENSOR UPPER SWMTH LOWER SWMTH EMERGENCY

C:0, S:46 10 0,00
Sens=#3 Lcell=#4

No	Result	Lower...	Upper...	Date	Time


Start **Stop**





Measurement process starts by creating traces on the material

Monitoring the process of creating a starting position and the device returns to its stops.

Press Start button to start measurement



After you create something like the following figure in the window to create the image. From left to right and from top down approach from the buttons to perform the measurement.



To make precise measurements must be measured normal once, then tab precise measurement precision approach allows you to make more accurate your measurements you can use the button.

The interface displays the following data and controls:

No	Result	Lower...	Upper...	Date	Time

Control Panel Data:

Min.	Average	Max.	Std.Dev.
0		0	


Test Parameters:

Test Data	Manual Indenter Movement	Test	Sensitive Test
Month	September	Year	2010
Test Nr	20100915_172135	Zoom	150
LowerLimit	200,00	UpperLimit	450,00

No	Result		Lower...	Upper...	Date	Time
1	273.76	OK	200,00	450,00	22.09.2...	14:26:21

precise measurement of the left

precise measurement from the right



above approach

below approach



